





# 2005 Existing Traffic Conditions

## Legend

- -Study corridor
- - - -Rail line
-  -Signalized intersection
-  -Stop controlled intersection
-  -Movement is excessively delayed
-  -Queue caused by train crossing



Cyclist Travels on Narrow Shoulder



Trucks Pass on Redwood Road



Truck Turns Left from 2600 South

Vehicle Turning Left from 500 S Blocks Thru Traffic

4 peak hour train crossings (Union Pacific) approximately 2-5 minutes each

## 2030 No Build Conditions

4 peak hour train crossings (Union Pacific) approximately 2-5 minutes each plus 6 peak hour UTA train crossings. Max. delay 1.5 min. each

**Average N/E Travel Times – PM Peak Hour**  
Existing 2005 = 7 mins.  
2030 No Build = 9 mins.